Christopher B. Gray GALLATIN COUNTY ATTORNEY'S OFFICE 1709 W. College St., Suite 200 Bozeman, Montana 59715 406-582-3745

ATTORNEY FOR GALLATIN COUNTY

2012 FRY 25 PT 3 41

BE BENTY

EIGHTEENTH JUDICIAL DISTRICT, GALLATIN COUNTY, MONTANA

GALLATIN COUNTY, MONTANA,)	Case No.: DV-12 - 367 A
)	
Plaintiff,)	COMPLAINT
)	
)	no summing
vs.)	
)	
THE DURRANT GROUP, INC.,)	
)	
Defendant.)	

Plaintiff, Gallatin County, by and through its undersigned counsel of record, files this complaint:

PARTIES

- Plaintiff, Gallatin County (County) is a political subdivision of the State of Montana governed by its elected Board of County Commissioners which has the legislative and executive powers set forth in Montana law.
- Defendant, The Durrant Group, Inc. (Durrant) is a Wisconsin corporation with offices in Denver, Colorado and provides architectural services.
- Durrant through its agents is licensed to do business in the State of Montana and at all times relevant to this complaint transacted business and committed acts in the State of Montana.

JURISDICTION AND VENUE

 The jurisdiction of this court is invoked pursuant to Montana law and agreement of the County and Durrant. Performance of contracts and commitment of acts have occurred in Gallatin County, Montana. Venue is therefore proper in this court. The County and Durrant have also agreed that venue is proper in this court.

FACTS

- 5. On or about March 5, 2008 the County and Durrant entered into a contract by which Durrant agreed to perform certain architectural services including the preparation of plans and specifications for the construction of the new Gallatin County Detention Center (Detention Center) located in the City of Bozeman. The terms and conditions of that contract were modified numerous times during the course of performance of the contract.
- Beginning in May of 2009 during the course of performance of the contract the County notified Durrant of its design defects and deficiencies for the Detention Center project.
- 7. As the Detention Center project continued the County continued to notify Durrant of additional design defects and deficiencies a summary of which are set forth in Exhibit A of this complaint which is attached and incorporated by reference.
- The County additionally disclosed to Durrant design defects and deficiencies related to certain mezzanine doors in the Detention Center the costs of which exceeded those set forth in Exhibit A.
 - 9. Additional design defects and deficiencies have been discovered by the County.
- 10. The County being wholly untrained in the matters connected with the design and construction of a Detention Center relied on the acts, recommendations and advice of Durrant in the architectural services it performed for the Detention Center project.
- On or about December 15, 2011 Durrant notified the County that the Detention Center project was complete.
- On or about January 26, 2012 Durrant filed for bankruptcy protection in the United States
 Bankruptcy Court in the Northern District of Iowa, Case No. 12-00110.
 - 13. On May 17, 2012 Durrant's petition in bankruptcy was dismissed.
- 14. From the point in May 2009 where the initial design defects and deficiencies were disclosed to the filing of bankruptcy by Durrant in January of 2012, the County intended to mediate disputes pursuant to the requirements of the contract it entered with Durrant.

CLAIMS FOR RELIEF

Count I - Breach of Contract

- 15. Plaintiff incorporates the allegations of Paragraphs 1-14 above as restated here in full.
- 16. The contract between the County and Durrant as entered and modified is supported by good lawful consideration and is legally binding and enforceable against Durrant.
- 17. The contract between the County and Durrant as entered and modified obligates.
 Durrant to perform certain architectural services for the Detention Center project.
- Durrant failed to perform architectural services under the contract between the County and Durrant.
- 19. Durrant's failure to perform constitutes breach of contract including breach of corresponding warranties and covenants of good faith and fair dealing.
- Durrant's breach has caused Gallatin County damages in an amount to be determined at trial.
- 21. The contract between the County and Durrant as entered and modified sets forth that attorney's fees and costs are to be paid to a prevailing party in the event of a dispute.

Count II - Negligence

- 22. Plaintiff incorporates the allegations of Paragraphs 1-21 above as restated here in full.
- 23. Durrant by agreeing to provide the County certain architectural services for the Detention Center project was obligated to exercise ordinary and reasonable care and skill in providing those services to the County.
- 24. Durrant breached its duty to use ordinary and reasonable care and skill in providing architectural services to the County.
- 25. As a direct and proximate result of that Durrant's negligence the Detention Center project contains design defects and deficiencies and the County has had to remedy those design defects and deficiencies at additional cost.
- 26. The value of the damages to the County based on Durrant's design defects and deficiencies are in an amount and cost to be determined at trial.

PRAYER FOR RELIEF

WHEREFORE, Plaintiff respectfully request this court grant the following relief:

- 1. Award Plaintiff damages in an amount to be determined at trial;
- Award Plaintiff all costs and expenses of this action, including attorneys fees, to the extent allowed by law; and
- 3. Award such additional relief the court deems proper to the Plaintiff.

DATED this 25th day of May, 2012.

GALLATIN COUNTY ATTORNEY'S OFFICE

Christopher B. Gray

Chief Deputy County Attorney

EXHIBIT A

Change Order	and the second districts			[[[[[[[[[[[[[[[[[[[[
Number	Bulletin Number	Basis	Responsible Discipline	Description of Scope change (Potential Design Error/Omission)	Total Cost of Change per CMAR
CMAR CO S	Builetins 332	COB Sig Opt Review comments, CMAR RFI 018	Carrent	Code Compliance (Structural - Rebar required by Building Code	\$24,139.01
CHINI CO /	Bulletine 005	CMAR RFI 052	Civil	Manhole required, incorrect elevation	\$6,957.32
	Burietow (A)	CMAN RP1052	CIVIL	Interior require, incorrect services	p0,537-34
CMAR CD 2	Bulletina DOS	CMAR RFI 028	Security	Security Components required by Program	\$5,764.58
CMAR CO 3	Bulletine 007	DUI Relocation Sitewalk	Architectural	OUI move-related changes	58,153.43
	Bulletins 014	CMAR RFI 107	Architectural	Minor Architectural change - shift wall to encompass electrical	\$464.06
CRARE CO. 4	Budston Chr.		****	Code Commission Blanking	£21 304 00
CMAR CD 4	Builetine 020	CMAR RFI 141, 136, 103, 103e	Mechanica!	Code Compliance: Plumbing	\$21,394.91
- Salaries	Bulletin# 022	CMAR RFI 147	Structural	Structural Requirement change to scope	\$1,704.17
	Bulletin# (123	CMAR RFI 143	Structural	AHU bearing inadequate	\$44,943.76
	Bulletinil 024	ASI 024	Structural	Structural Requirement, change to scope	\$919.96
CMAR CD 6	Bulletine 029	CMAR RFI 198	Structural	Insufficient detail at structural component (corbel)	59,222.04
	Bulletine 030	CMAR RFI 174, 174a	Electrical	Electrical drawings failed to include electrical support at ty	\$2,077.31
	Bulletin# 035	Security Glazing sitewalk	Security	Security glazing not adequate at frames separating multi-purpose room from comdor	\$5,390.00
CMAR CD 7	Bulletina 039	CMAR RFI 236, 237	Mechanical	Missed drains at showers	5340.38
CHANGE CO. 7	Bulletin# 040	ASI 032	Security	Security error - Glazing at entrances	51,107.83
Various III	Duriting 1990	NA VAL	PECCHINY	Consumy with Commy of Commission	21,007.00
CMAR CO B	Bulletin# 050	Submittal 094	Architectural	Fire rating requirements at door (detention area)	\$6,360.45
	Builetine 051	CMAR RFI 067	Security	Security covering for below-mezzanine sprinkler pipe	\$5,376.32
	Bulletin# 055	CMAR RFI 242	Structural	Need to add steel supports at roof decking	\$632.65
				Drawings did not reflect required slope at VSP floor- deduct from	
CMAR CO 9	Bulletin# 058	CCD 005, ASI 626, CMAR RFI 270	Architecturai	Constuction Contingency	\$2,258.18
	Parameterate		Civil (also,		
	Bulletin# 059	ASI 026a, CMAR RFI 261	Mechanical)	Add trench drain, remove roof drains	\$907.66
CMAR CO 10	Bulletina 063	CMAR RFI 267, 268	Architectural	Fire rated glazing at speaker port location	\$1,324.02
CMAR CO IO	Builetine 064		Structural	Add additional steel at entrance ganopy	52,006.92
	Bulletin# 065	CMAR 8F1 287s, 288	Architectural	Add door drop plates to support required hardware assemblies	\$279.28
	THE RESERVE AND ADDRESS OF THE PERSON NAMED IN	CMAR RFI 292R, 292s	Mechanical	Required to meet with AHJ requirements at meter location	\$5,303.62
_	Bulletin# 070	CMAR RFI 305a	Mechanical	response to meet with AAS requirements at meet scaled	35,303.62
CMAR CD 11	Bulletina 072	CMAR RFI 305a	Mechanical	Roof Drainage vertical run had to be re-routed	\$9,189.73
COUNTY FOR A S	Businestern service	School In Consultation	in charine	Skylights required additional termination ber beyond accepted	
- Laigneine	Bulletine 073	CMAR RFI 317	Architectural	submittal	\$3,466.09
CAAAA CO 13	B. Haring and	71445 BC 0675	Element.	Lights at showers below Mezzanine	\$10,313.80
CMAR CD 12	Bulletin# 077	CMAR RFI 067a	Electrical	Unsatisfactory finish at exposed beam/wall sections	\$2,788.28
	Bulletinit 079	CMAR RF: 340, 341	Architectural	Water lines required re-route due to pre-cast beam	\$6,347.22
	Bulletine 080	CMAR RFI 325	Mechanical		5527.69
	Bulletin# 081	CMAR RFI 339	Mechanical	Cost for adding sprinkler coverage Specification interpreted as allowing wooden transaction. Owner	3527.09
	Bulletin# 082	ASI 038	Architectural	required metal transaction drawer	\$3,150.06

EMAR CO 13	Bulletin# 086	TRFI 016	Architectural	Locksets do not follow pattern for interior/exterior sallyport operation and the County's operational expectation	\$8,303.33
	Bulletina OSS	ASI 044	Architectural	Provide for minimum security expectation at joints created between both similar and disimilar wall types.	\$5,374.55
	Bulletin# 091	CMAR RFI 357	Architectural	Specified recessed fixtures in exposed condition at front canopy	\$585.16
	Bulletin# 095	ASI 045	Security	Security Electronics falled to provide for ability to communicate through barrier	\$5,625.24
CMAR CO 14	Bulletine 101	CMAR RFI 381	Mechanical	Need to add mixing valves at showers, not shown on dwgs.	\$1,950.15
CMAR CO 15	Bulletine 120	TRFI 051	Mechanical	Incorrect shower unit (detachable ADA shower hose) and non- detention grab bars.	\$83,750.51
	Bulletine 121	CMAR RFI 408	Electrical	Missed light in corridor that connects GP Rec with Dayroom for Fire Evac.	\$1,258.40
CMAR CD 16	Builetina 134	CMAR RFI 418 Response		Wrong glazing type, needed to be security glazing	\$508.42
CMAN CD III	Bulletine 139	CMAR RFI 372, TRFI 041	Security	Modesty panel designs did not adequately provide expectation for line	\$9.945.78
	Boulding 733	CMSAR 901 372, 1901 041	Architectural	of sight security posture	39,945.78
CMAR CO 17	Bulletin# 125	TRFI 50	Architectural	Door stops created tripping hazard and code-compliance issue.	\$4,176.82
	Bulletinit 155	CMAR RFI 421	Mechanical	Add not and cold water (rather than tempered) at mop sink	\$1,197.73
	Buileting 159	CMAR RFI 441	Mechanical	RATP at Central Control scope change	59,117.78
	Builetin# 160	CMAR RFI 448	Security	Add cemeras at Staff Sally Port and comdor	510,848.19
911	Bulletine 161	TRFI 068	Architectural	Officer station designed and mounted too low for design intent (standing Officer station)	\$1,168.84
	Bulletina 163	TRF1 065	Security	Provide inmate phones at GP Mezzanine level	\$4,526.29
	Bulletin# 269	CMAR RFI 454	Security	Add locking hardware at Lobby exit doors.	\$3,032.01
CMAR CO 18	Bulletink 172	TRF1 071	Security	Correct line of sight error at A pod	511,347.32
Marine Consultation	Bulletin# 175	CMAR RFI 462	Electrical	Including lighting relay wiring for Dormitory bethroom lighting	\$5,671.66
CMAR CO 19	Bulletin# 198	CMAR RFI 472	Mechanical	Replicate water control in first floor dormstory as in second floor dormstory	\$5,181.34
CHINA CO 33	Bulletina 199	CMAR RFI 477	Mechanical	Shower exhaust reroute at Male GP unit	\$4,374.55
	Bulletin# 222	CMAR RFI 494	Electrical	Relays at Kennuli futures for battery operation	\$7,749.79
	Bulletin# 223	CMAR RF1496 Rev	Electrical	Track lighting power supply 120V rather than 277V as designed	\$1,117.49
CMAR CO 20	Bulletine 200	CMAR RFI 4E3	Civil	Missing concrete splash pan for drainage from roof	\$2,299.38
E Entire las Las debatronis de com Entire las Las debatronis de com	Bulletin# 205	TRFI 095	Architectural	Rubber cove base at all floor to wall intersection (minus doorframes)	\$4,769.51
	Bulletin# 212	CMAR RFI 063a-Rev	Electrical	Missing emergency power at VSP OH door function	\$4,271.65
	Bulletin# 215	ASI 062	Electrical	Power and transformer for irrigation pump	\$5,139.40
RITE.	Bulletin# 216	CMAR RFI 489	Mechanical	Missing backflow preventors at Double Steamer in Kitchen	\$1,009.34
CMAR CO 21	Bulletine 226	CMAR RFI 502	Electrical	Emergency power at emergency exit signs	\$1,299.05
The same of the sa	bulletin# 227	CMAR RFI 482	Mechanical	Missing duct detectors in chases	\$3,003.36
	Bulletine 228	CMAR RFI 507	Mechanical	Code requirement adding amoke detector in sub-dayroom, Fernale Maximum	\$1,326.47
				Code requirement modification to correct door swing issue at	
CMAR CO 22	Builetinit 230	CMAR RF1 476	Architectural	mezzanine doors x 42	\$5,167.59

Bulletine 231	CMAR RFI 510	Electrical	Emergency power at smoke dampers in Dayrooms, per IBC 4.6	\$5,410.85
Bulletine 232	CMAR RFI 513	Architectural	Code requirement for handraits at booking platform steps, per AHJ	\$790.66
Bulletin# 233	CMAR RFI 512	Mechanical	Code requirement, provide smoke detectors, per AHJ	\$3,181.26
Bulletin# 234	CMAR RFI 494a	Electrical	Code requirement, install relays at lights to function properly during emergency power	\$2,637.07

\$ 369,927.78